

September 8, 2010: Impoundment at Evick Property - Photograph Log





Photo ID:
P9080236.JPG
Date:
9/8/2010
Description:
Culvert at base of impoundment berm



Photo ID:
P9080238.JPG
Date:
9/8/2010
Description:
Fill around tree

	Photo ID: P9080235.JPG
	Date: 9/8/2010
	Description: Looking down at filled wetland from impoundment berm; stream visible near center of photo